




Reversing levers – 3/64" brass sheet




Meteor and other small motors commutator




.007" phosphor bronze contact plate. 3 are needed.




.0625 (1/16") paxolin base




Assemble the unit by pushing the lugs of three plates into the base holes and bending back underneath





Reversing lever brass bush and phosphor bronze spring washer



Early Comet Brush (7 thou phosphor bronze)



Later Comet Brush (7 thou phosphor bronze)



Two types of Meteor/other small motor brush – one dished and the other plain. Made in 7 thou phosphor bronze

Taycol replacement parts from Taycol.hobby-site.com. Issued free under Creative Commons copyright.